

SPECIFICATION AMENDMENTS

In the second paragraph appearing on page 19, please replace the following paragraph:

Adaptor ~~232~~ collar 212 is also provided with a plurality of concavities 236 which are equiangularly spaced about side wall with a respective concavity 236 being located medially between a pair of bores 232, as is shown in Figure 17. Each concavity 236 includes a hemispherical portion 238 that is generally in a common transverse plane as are the axes of bores 232. Hemispherical portion 238 communicates with an inclined wall portion 240 that extends obliquely to outer surface 242 so as to be oblique to the central axis of adaptor collar 212.